## Railroad Equipment and Load-out Yards

DMME
Division of Mineral Mining
AR Training

# Part IX Mobile Equipment 4VAC25-40-1590

- Railroad equipment is inherently dangerous due to:
  - The size and weight of the equipment.
  - The time delay involved in starting and stopping railcars.
  - Poor sight-lines and distances.
  - Communication usually limited to radios and hand signals.
- The 18 subsections of 4VAC25-40-1590 deal with these and other hazards.

## **Railroad Crossings**

#### ■ 1590.1 says, in part:

 Crossings shall be posted with warning signs or signals or shall be guarded when trains are passing.

#### **1**590.4

 Only authorized persons shall be permitted to ride on trains or locomotives and they shall ride in a safe position.



2007 fatality: miner riding the end of the cars was killed when the cars struck a haul truck crossing the tracks.

## **Sounding Warnings**



2007 fatality: miner walking across rail yard struck by a moving locomotive.

#### **1590.2**

Operators shall sound
 a warning before
 starting trains and
 when trains approach
 crossings, other trains
 on adjacent tracks,
 persons, and any place
 where vision is
 obscured.

## **Passing Between Cars**

#### **1590.3**

Persons shall not go
over, under, or
between cars unless
the train is stopped
and the motorman has
been notified and the
notice acknowledged.



2004 fatality: A miner was helping to position cars. After giving the motorman the go-ahead to move, the miner was found beside the tracks, apparently run over by the cars.

## Clearance Between Cars



2002 fatality: While switching cars at night, the switchman was caught between the moving cars he was riding and a stationary car on an adjoining track.

#### **1590.14**

 Railcars shall not be left on side tracks unless ample clearance is provided for traffic on adjacent tracks.

## **Brakes and Blocking**

#### **1590.15**

 Parked railcars, unless held effectively by brakes, shall be blocked securely.

#### **1590.16**

 Railroad cars with braking systems shall be equipped with effective brake shoes when in use.



2001 fatality: cars being moved using a rubber tired tractor mounted with a car coupler. A miner stepped between the tractor and cars to position the couplers. The cars rolled forward, pinning the miner between the couplers.

## Other Important Subsections

### **1**590.6

 Positive-acting stop blocks, derail devices, track skates, or other adequate means shall be installed wherever necessary to protect persons from runaway or moving railroad equipment.

#### **1590.11**

 Roadbeds, rails, joints, switches, frogs, and other elements on railroads shall be designed, installed, and maintained in a safe manner consistent with the speed and type of haulage.

#### **1590.17**

 Where necessary, bumper blocks, or the equivalent, shall be provided at all track dead ends.

## And Most Important....

- **1590.8** 
  - Persons in charge of trains (motormen, brakemen, yard masters, etc.) shall ensure that tracks are clear and personnel are in safe locations prior to moving trains.



## Rail/Loading Yards

- 4VAC25-40-1600
  - Persons shall remain clear of mobile equipment in operation and shall not work or pass under booms or buckets of equipment in operation.
- 4VAC25-40-1460.5
  - Persons shall not be transported between cars of trains.



2006 fatality: miner walking beside tracks is struck by front end loader.

## Loading

- 4VAC25-40-1610
  - Chute-loading installations shall be designed so that the persons pulling chutes are not required to be in a hazardous position while loading cars or trucks.